

From: [Garyg Miller](#)
To: [Rita Engblom](#)
Subject: Fw: Gulfco 1974 Aerial Photograph
Date: 05/12/2010 12:03 PM
Attachments: [1974GoogleEarth_Image.jpg](#)

Rita,

This shows the additional area (south of & adjacent to the former impoundments) to be included with the cap repair.

Gary Miller, P.E.
Remediation Project Manager
EPA Region 6 - Superfund (6SF-RA)
(214) 665-8318
miller.garyg@epa.gov

----- Forwarded by Garyg Miller/R6/USEPA/US on 05/12/2010 12:01 PM -----

From: "Eric Pastor" <eric.pastor@pbwllc.com>
To: Garyg Miller/R6/USEPA/US@EPA
Date: 04/19/2010 03:49 PM
Subject: Gulfco 1974 Aerial Photograph

Hi Gary –

Per my voice mail, attached is a 1974 aerial photograph we just discovered that shows the buried debris area south of the former surface impoundments. Please call me to discuss.

Thanks.

Eric Pastor
Pastor, Behling & Wheeler, LLC
2201 Double Creek Drive, Suite 4004
Round Rock, Texas 78664
512-671-3434



1974GoogleEarth_Image.jpg